## MALSR LED SIR Questions/Answers

1. Section B2 – Part I CLIN 1005 is identical to CLIN 1005b. Was CLIN 1005 intended to be a roll-up summary CLIN of 1005a and 1005b or should the CLIN Price be identical for CLIN 1005 and CLIN 1005b?

Answer: Please see Section C.3.2.5, referencing PRD sections 3.1.2.6 and 3.2.2.6. The contractor shall designate which CLIN represents the low wave length band and the high wave length band.

2. Section B2 – Part I CLIN 1006 is identical to CLIN 1006b. Was CLIN 1006 intended to be a roll-up summary CLIN of 1005a and 1005b or should the CLIN Price be identical for CLIN 1006 and CLIN 1006b?

Answer: Please see Section C.3.2.5, referencing PRD sections 3.1.2.6 and 3.2.2.6. The contractor shall designate which CLIN represents the low wave length band and the high wave length band.

3. Section B3 – Part I CLIN 2001 is identical to CLIN 2001b. Was CLIN 2001 intended to be a roll-up summary CLIN of 2001a and 2001b or should the CLIN Price be identical for CLIN 2001 and CLIN 2001b?

Answer: Please see Section C.3.2.5, referencing PRD sections 3.1.2.6 and 3.2.2.6. The contractor shall designate which CLIN represents the low wave length band and the high wave length band.

4. Section B3 – Part I CLIN 2002 is identical to CLIN 2002b. Was CLIN 2002 intended to be a roll-up summary CLIN of 2002a and 2002b or should the CLIN Price be identical for CLIN 2002 and CLIN 2002b?

Answer: Please see Section C.3.2.5, referencing PRD sections 3.1.2.6 and 3.2.2.6. The contractor shall designate which CLIN represents the low wave length band and the high wave length band.

5. Please clarify the requirements for a "Letter of System Adequacy" as specified in Section L, Para. L.17.3.2. Can you please clarify how this relates to a feasibility study?

Answer: An amendment has been made to this SIR, deleting Section L.17.3.2. This is not a requirement.